## HISTORIC AMERICAN BUILDINGS SURVEY

13-11-

## INDEX TO PHOTOGRAPHS

Commercial and Industrial Buildings,

McFadden Coffee and Spice Company Factory and Warehouse 145 First Street Dubuque Dubuque County

HABS No. IA-I60-H

1owa

Documentation: 7 exterior photos (I987) 7 interior photos (1987) 1 measured drawing (1987)

3 data pages

Clayton B. Fraser, Fraserdesign, photographer, July 1987.

(1988)

IA-160-H-I EAST SIDE AND NORTH REAR. VIEW TO SOUTHWEST.

EAST SIDE AND SOUTH FRONT. VIEW TO WEST. IA-160-H-2

SOUTH FRONT AND WEST SIDE. VIEW TO NORTH. IA-160-H-3

IA-160-H-4 WEST SIDE AND NORTH REAR. VIEW TO SOUTHEAST.

EAST SIDE DETAIL. VIEW TO NORTHWEST. IA-160-H-5

SOUTH FRONT DETAIL, SHOWING FRONT DOOR. VIEW TO NORTH. IA-160-H-6

EAST SIDE DETAIL, SHOWING PAINTED COMPANY SIGN. VIEW TO WEST. IA-160-H-7

1A-160-H-8 FIRST FLOOR OFFICE (NOW RETAIL SALES) SPACE. VIEW TO NORTH.

1A-160-H-9 THIRD FLOOR ELEVATOR HALL, VIEW TO EAST.

1A-160-H-10 THIRD FLOOR COFFEE AND SPICE MILLING ROOM (NOW TIRE STORAGE),

LOOKING TOWARD ELEVATOR HALL. VIEW TO NORTHWEST.

FOURTH FLOOR WAREHOUSE (NOW TIRE STORAGE). VIEW TO NORTH. IA-160-H-II

FOURTH FLOOR ROASTING ROOM (NOW TIRE STORAGE). VIEW TO SOUTH. 1A-160-H-I2

IA-160-H-I3 FOURTH FLOOR ROASTING ROOM, SHOWING CLERESTORY. VIEW TO SOUTH.

IA-160-H-14 CONCRETE COLUMN/BEAM DETAIL. VIEW TO WEST.

For general information, see HABS No. IA-160.